
REV.	DESCRIPTION/ECO NO.	DATE
	RELEASED	3/24/10



NOTES:
1. OPENING FOR FLEX TAPE.
2. OPERATION:
   1. GENTLY PULL DARK TABS OUT.
   2. INSERT FLEX TAPE WITH CONTACTS UP
   3. PUSH DARK TABS BACK IN TO LOCK FLEX TAPE IN PLACE.
   4. DO NOT USE WITH CONTACTS THAT HAVE SOLDER BUILD UP.
3. LIMIT CURRENT TO A MAXIMUM OF 5 AMPS.

METRIC THIRD ANGLE PROJECTION	DIMENSIONS ARE IN MILLIMETERS TOLERANCE UNLESS OTHERWISE SPECIFIED 1 PL +/- REF. 2 PL +/- REF. ANGLE +/-	JKL COMPONENTS CORPORATION TITLE: NO SOLDER FLEX TAPE CONNECTORS					
DRAWN BY: L. WENGSTROM	APP'D BY: L.R.	DATE: 3/24/10	SIZE: A	FSCM NO.: 55335	DRAWING NO.: ZFS-CH0-J		
- CAD DRAWING - MANUAL REVISIONS NOT PERMITTED	SCALE: NOT TO SCALE	RELEASED DATE: 3/24/10	REVISION DATE:	REV. NO.:	SHEET: 1 OF 1		