
REV.	DESCRIPTION/ECO NO.	DATE
	RELEASED	3/24/10



NOTES:

1. OPENING FOR FLEX TAPE.
2. OPERATION:
   1. GENTLY PULL DARK TABS AWAY FROM WIRES
   2. INSERT FLEX TAPE WITH CONTACTS UP
   3. PUSH DARK TABS BACK TOWARDS WIRES TO LOCK FLEX TAPE IN PLACE.
   4. DO NOT USE IF CONTACTS HAVE SOLDER BUILD UP ON THEM.
3. LIMIT CURRENT TO A MAXIMUM OF 5 AMPS.

METRIC THIRD ANGLE PROJECTION	DIMENSIONS ARE IN MILLIMETERS TOLERANCE UNLESS OTHERWISE SPECIFIED 1 PL +/- REF. 2 PL +/- REF. ANGLE +/-	JKL COMPONENTS CORPORATION					
		TITLE: NO SOLDER FLEX TAPE CABLE CONNECTOR					
DRAWN BY: L. WENGSTROM	APPV'D BY: L.R.	DATE: 3/24/10	SIZE: A	FSCM NO.: 55335	DRAWING NO.: ZFS-CH205-J		
- CAD DRAWING - MANUAL REVISIONS NOT PERMITTED			SCALE: NOT TO SCALE	RELEASED DATE: 3/24/10	REVISION DATE:	REV. NO.:	SHEET: 1 OF 1